

Carnage Report

Written by slinky

Sunday, 15 June 2008 23:12 - Last Updated Friday, 20 June 2008 21:27

Pictures speak a thousand words, most of them unprintable..

{gallery}RV1/carnage/{/gallery}

This is pretty much as bad as it gets. The heads are cracked and some valves are bent. Even the Jesel drive is damaged! The only things useable are the valve springs, retainers, T+D rockers, intake and rocker covers. It's a sobering sight when you take the oil pan off and see this... More pics when Nigel sends me them over...